09-June-2026

Shul and Mikvah

Based on the attached exhibit and data sheet presented, showing the locations of FH 31 and 33, the two locations mentioned are in compliance with required water supply and access and acceptable to proceed with construction.

Respectfully,

Herb Smith

Fire Inspector

(CAP) Bureau Veritas