

A Team Fire Sprinklers, Inc.

Inspections, Maintenance, Testing, Design & Installations

2338 NW 151 Street Opa Locka, Fl 33054

Tel: (305) 948-3473* Fax *1 (888) 637-7504

INSPECTION TEST & MAINTENANCE OF FIRE HYDRANT SYSTEM

☐ QUARTERLY ☐ SEMI ANNUAL ☒ ANNUAL

Property Name: **Synogogue South**
Address: **28020 FL-78**
Okeechobee, Fl 34974

Date of Inspection: **03/24/2026**
Inspected by: **Jerry Fleurinord**

Location: 31# Hydrant

Notes
Shut Off Valve: 8" RoadBox

Read 1 # Hydrant
65 psi **Static Pressure**
32 psi **Residual Pressure**
38 psi **Pilot Pressure**

Outlet	Size	Pilot Pressure	Flow
		Flow Hydrant	
#31	2 ½"	38 PSI	1149 GPM

1. Did hydrant flow clear up?_____ ☒ YES ☐ NO ☐N/A
2. Bolts, nuts and gaskets free of corrosion?_____ ☒ YES ☐ NO ☐N/A
3. Are caps and chain in place of hydrant? _____ ☒ YES ☐ NO ☐N/A
4. Hydrant properly drained? _____ ☒ YES ☐ NO ☐N/A
5. Hydrant clearance 15' _____ ☒ YES ☐ NO ☐N/A
6. Did hydrant operating nut free open and closed? _____ ☒ YES ☐ NO ☐N/A

Comments: _____

Inspections, Installations, Service, & Design

24 Hour Emergency Services